

American Ultra HSS Wiring


011-8020/8022

- 1: Neck
- 2: Neck + Middle
- 3: Middle
- 4: Middle + Bridge
- 5: Bridge

S-1 activates neck
in pos 4 & 5

Tone 1: Neck+Middle
Tone 2: Bridge PU

Treble bleed can be
replaced with ordinary
caps and resistors



08.2.2026
Rev.A

www.axefiles.com

Graphics by Gerry Haze. all rights reserved